

TOOLBOX TALKS/SAFETY TALKS

Training & Education

Pinch Points

Recently, a worker was crushed to death against a wall by a huge truck that was backing up. That was a pinch point accident.

In another instance, a pair of pliers slipped and pinched a worker's hand, which caused ablood blister.

Pinch point conditions are one of the most difficult hazards to guard. For example, let's lookat a set of two inrunning calendar rolls used to finish cloth or manufacture paper or rubber. The material in the process must reach the in-running rolls to be carried through; no guardcan be placed at the immediate point. There are some partial guards on such equipment, but operators must exercise extreme caution and alertness when these rolls are running, which is usually at a very high speed and under considerable pressure.

Closely stored 55-gallon steel drums, when moved or handled, create pinch points between each other or the dolly being used to move them. Because the drums are round, they are more difficult to handle and control in many cases. Here the only protection is care and alertness.

The same thing applies to heavy crates, castings, and boxes that are stacked close to eachother.

Improperly guarded punch presses can inflict more serious injuries. However, most punchpresses are well guarded by a two-hand trip and photoelectric beams. These must be used with part-revolution presses; they cannot be used with full-revolution presses. Fullrevolution presses must have a guard-barrier, two-hand control, or similar positive device. Proper guarding prevents entry over, around, and through.

It is dangerous to work around machinery that has oscillating or reciprocating parts or elements. Of course, most of these areas are guarded, but in cases when guards are removed to do work or make adjustments, be sure the parts cannot move or be moved. Tagout or lock out the equipment and be sure the machinery cannot cycle if it is off balance or activated by accident.

There are many commonplace things that are potential pinch points, like heavy steel doorsor heavy covers for bins or hoppers, and often there is no way to guard these hazards. Careis your only safeguard. Even extension ladders can create serious pinch points, the rungssliding past each other can catch fingers, hands, and feet. Roller, belt, or chain conveyors create many pinch points. On a roller-skate-wheelconveyor, heavy crates, castings, and other materials that are too close together can evencut off a finger. Powered conveyors are most dangerous at floor openings and at thebeginnings and ends, if they run inclined between different levels.

A little thought will bring to mind the many pinch points (sometimes called nip points) herein our own operation. Let's discuss some of them now.

Disclaimer: This website and the information contained in the Injury & Illness Prevention Program (IIPP) are intended and authorized for the use of employees of this Company only; they are not intended for, nor should they be used by, the general public or any third parties. If you have not been expressly directed to this site by the Warner Bros. Studio Operations Department of Safety & Environmental Affairs, you are not authorized to use this website and you must exit now. The IIPP is a general outline of safe work practices to be used as a guideline for our productions to provide a safe work environment for our employees. Because each particular work situation is different, these IIPP guidelines are intended to be used in conjunction with consulting the appropriate production supervisors and seeking the assistance of our Production Safety personnel. The information contained in this IIPP is not a legal interpretation of any federal, state or local regulations, laws or standards. No warranty is made about any of the contents of this website.